

Technical Information

Cerabar T PMC131, PMP131, PMP135

Pressure Transducer

With ceramic and metal sensors

For absolute pressure and gauge pressure measurement up to 400 bar
Extremely stable, overload-resistant and reliable



Application

Cerabar T is a pressure transducer for measuring absolute pressure and gauge pressure in gases, vapors, liquids and dusts.

Hygienic and threaded connections are available as process connections.

Your benefits



This compact pressure transducer impresses with its well-engineered construction:

- High reproducibility and long-term stability.
- Finely graduated measuring ranges from vacuum up to 400 bar/6000 psi.
- Ceraphire® ceramic sensor: corrosion-proof, abrasion-proof and extremely overload-resistant.
- Deployed for pressure monitoring up to SIL 2 as per IEC 61508/IEC 61511-1
- Sensors
 - Dry capacitance ceramic sensor (Ceraphire®) for measuring ranges up to 40 bar: overload-resistant, vacuum-proof, stable against alternating load
 - Piezoresistive sensor with metal diaphragm for measuring ranges up to 400 bar

Table of contents

Function and system design	3	Operating conditions (process)	11
Device selection	3	Process temperature range	11
Measuring principle	3	Overload resistance	11
Measuring system	4	Vacuum resistance	11
Input	4	Pressure specifications	11
Measured variable	4		
Measuring range	4		
Output	4		
Output signal	4		
Load	4		
Output signal	4		
Output current	4		
Power	5		
Switch frequency	5		
Input PLC	5		
Inductive loads	5		
Power supply	5		
PMC131	5		
PMP131 and PMP135	6		
PMP131	7		
Supply voltage	7		
Residual ripple	7		
Cable entry	7		
Performance characteristics	8		
Reference operating conditions	8		
Long-term stability	8		
Maximum measured error of analog output (under reference operating conditions)	8		
Switch point	8		
Rise time (T90)	8		
Settling time	8		
Thermal change of the lower range value and the span	9		
Temperature coefficient (TK) for lower range value and span	9		
Operating conditions (Installation instructions)	9		
Orientation	9		
Installation instructions	9		
Location dependence	9		
Operating conditions (environment)	10		
Ambient temperature range	10		
Storage temperature range	10		
Climate class	10		
Degree of protection	10		
Vibration resistance	10		
Electromagnetic compatibility	10		
Mechanical construction	12		
PMC131	12		
PMP131 and PMP135	13		
PMP131	13		
PMP135	14		
Weights	15		
Material	15		
Operating elements	15		
Operating elements	15		
Certificates and approvals	17		
CE mark	17		
Ex approvals	17		
Pressure Equipment Directive (PED)	17		
Functional safety SIL 2	17		
Suitability for hygienic processes	17		
TSE Certificate of Suitability	17		
Standards and guidelines	17		
Registered trademarks	17		
Ordering information	18		
PMC131	18		
PMC131 (continued)	19		
PMP131	20		
PMP131 (continued)	21		
PMP135	22		
Accessories	23		
Welding neck with sealing taper	23		
Welding neck with sealing surface	23		
Plug-in jack	23		
Plug-on display PHX20/PHX21	23		
Documentation	24		
Field of Activities	24		
Technical Information	24		
Operating Instructions	24		
Functional Safety Manual (SIL)	24		
Safety Instructions	24		

Function and system design

Device selection	Cerabar T	PMC131	PMP131	PMP135
		 P01-PMC131xx-14-xx-xx-xx-000	 P01-PMP131xx-14-xx-xx-xx-000	 P01-PMP135xx-14-xx-xx-xx-000
		With capacitive measuring cell and ceramic measuring diaphragm (Ceraphire®)	With piezoresistive measuring cell and metallic measuring diaphragm	With piezoresistive measuring cell and metallic measuring diaphragm for hygienic applications
Field of application	Absolute pressure and gauge pressure	Absolute pressure and gauge pressure	Absolute pressure and gauge pressure in hygienic processes	
Output	Current output 4 to 20 mA	<ul style="list-style-type: none"> – Current output 4 to 20 mA – Voltage output 0 to 10 V – Switch output PNP 	<ul style="list-style-type: none"> – 4 to 20 mA – Switch output PNP 	
Process connection	Thread: – G ½ – ½ MNPT and ¼ FNPT – G ½, bore 11 mm	Thread: – G ½ – ½ MNPT and ¼ FNPT – ½ MNPT, bore 4 mm – G ¼ – ¼ MNPT, bore 3.5 mm – M 20 x 1.5	Hygiene: – Clamp DN 22 (¾") – Tri-Clamp DN 25 to 38 (1" to 1½") – Tri-Clamp DN 40 to 51 (2") – G 1 – SMS 1½"	
Measuring range	–1 to 0 bar/–100 to 0 kPa up to 0 to 40 bar/0 to 4 MPa	0 to 1 bar/0 to 100 kPa up to 0 to 400 bar/0 to 40 MPa	0 to 1 bar/0 to 100 kPa up to 0 to 40 bar/0 to 4 MPa	
Process temperature	–20 to +100 °C	–25 °C to +70 °C	–25 to +100 °C (+135 °C for max. 1 hour)	

Measuring principle

PMC131


The measuring pressure causes a slight deflection of the ceramic diaphragm of the sensor. The pressure-proportional change in capacitance is measured at the electrodes of the ceramic sensor. The ceramic sensor is a dry sensor, i.e. no fill fluid is required for the pressure transfer. This makes the sensor completely suitable for vacuums. Extremely high stability, comparable with the material Alloy, is achieved by using ultrapure Ceraphire® as the ceramic.

PMP131 and PMP135 with analog output

The process pressure acting upon the metallic separating diaphragm of the sensor is transmitted to a resistance bridge via a fluid. The pressure-proportional change of the bridge output voltage is measured and processed further.

PMP131 and PMP135 with switch output

The process pressure acting upon the metallic separating diaphragm of the sensor is transmitted to a resistance bridge via a fluid. A differential amplifier creates a standard signal from the pressure-proportional change in output voltage of the bridge. A comparator with an adjustable hysteresis compares this signal with the pre-set switch point and then activates the transistor output.

Measuring system

1 PMP131, PMP135: current output with transmitter power supply unit, e.g. RN 221N from Endress+Hauser

2 PMP131, PMP135: switch output with load, e.g. PLC, DCS, relay

3 PMC131: voltage output with transmitter power supply unit, e.g. RIA452 from Endress+Hauser

4 PMC131: current output with transmitter power supply unit, e.g. RN 221N from Endress+Hauser

Input

Measured variable	Absolute pressure or gauge pressure
--------------------------	-------------------------------------

Measuring range	up to 400 bar/6000 psi, see Page 18, "Ordering information" section
------------------------	---

Output**Analog output (PMC131, PMP131, PMP135)**

Output signal	4 to 20 mA
----------------------	------------

Load	PMC131 $R_{Lmax} [\Omega] \leq (U_S - 1 V) / 0.02 A$
-------------	--

PMP131 and PMP135 (current output)

$R_{Lmax} [\Omega] \leq (U_S - 12 V) / 0.02 A$ (R_{Lmax} : Maximum load resistance, U_S : Supply voltage)

PMP131 (voltage output)

Load resistance $R_{Lmax} \geq 5 k\Omega$, current consumption $\leq 6 mA$

Switch output (PMP131, PMP135)

Output signal	PNP switch output (positive voltage signal), rate depends on power supply voltage
----------------------	---


Output current	<ul style="list-style-type: none"> ■ Switch status ON: $I_a \leq 500 mA$ ■ Switch status OFF: $I_a \leq 1 mA$
-----------------------	---

Power	max. 6 W
Switch frequency	max. 10 Hz
Input PLC	<ul style="list-style-type: none"> ■ Input resistance $R_i \leq 2 \text{ k}\Omega$ ■ Input current $I_i \geq 10 \text{ mA}$
Inductive loads	To prevent electrical interference, only operate an inductive load (relays, contactors, solenoid valves) when directly connected to a protective circuit (free-wheeling diode or capacitor).

Power supply

PMC131


Plug/cable connection



P01-PMC131xx-04-xx-xx-xx-001

Plug M 16 x 1.5 (DIN 43650/A), 1/2 NPT	Plug M 12x1	5 m/25 m cable
① Plug-in housing		① Reference pressure line
② Gasket		

Electrical connection: Analog/current output




1 Plug M 16 x 1.5 (DIN 43650/A), 1/2 NPT

2 Plug M 12x1

3 Cable (rd = red, bk = black, gnye = green-yellow)


P01-PMC131xx-04-xx-xx-xx-002

PMP131 and PMP135

Plug/cable connection

P01-PMP13xxx-04-xx-xx-xx-001

Plug M 16 x 1.5 (DIN 43650/A), 1/2 NPT Plug DIN 43650/C	Plug M 12x1	5 m cable, only analog output
① Plug-in housing	① Coupling nut	① Reference pressure line
② Plug-in jack with gasket	② Connector with gasket	
③ Coupling nut	③ Operating potentiometer (inner)	
④ Plug with O-ring		
⑤ Operating potentiometer (inner)		

Electrical connection: Analog/current output



P01-PMP13xxx-04-xx-xx-xx-002

1 Plug M 16 x 1.5 (DIN 43650/A), 1/2 NPT and plug DIN 43650/C

2 Plug M 12 x 1

3 Cable (rd = red, wh = white, gn = green)

For electrical connection provided by customer use only shielded cable

Electrical connection (switch output)1 *Plug M 16 x 1.5 (DIN 43650/A), ½ NPT*2 *Plug M 12 x 1*R *External load, e.g. relay, programmable logic controller, distributed control system**For electrical connection provided by customer use only shielded cable***PMP131****Electrical connection: Analog-/voltage output**1 *Plug M 16 x 1,5 (DIN 43650/A), ½ NPT and plug DIN 43 650/C*2 *Plug M 12 x 1*3 *Cable (rd = red, wh = white, gn = green)**For electrical connection provided by customer use only shielded cable***Supply voltage****PMC131**

11 to 30 V DC

PMP131 and PMP135 (current output, 2-wire version)

- For non-hazardous areas: 12 to 30 V DC
- Ex i: no-load voltage \leq 26 V DC, short-circuit current \leq 100 mA, power consumption \leq 0.8 W

PMP131 (voltage output, 3-wire version)

- 15...30 V DC

PMP131 and PMP135 (switch output)

- 18 to 32 V DC, current consumption without load $<$ 20 mA, with reverse polarity protection


Residual ripple

- Analog output: max. 5 % of supply voltage
- Switch output: max. 10 % of supply voltage

Cable entry

→ See Page 18, "Ordering information" section.

Performance characteristics

Reference operating conditions	as per DIN IEC 60770, $T_U = 25^\circ\text{C}$														
Long-term stability	$\leq 0.15\%$ of URL per year														
Maximum measured error of analog output (under reference operating conditions)	The measured error comprises the non-linearity including hysteresis and non-reproducibility in accordance with the limit point method as per IEC 60770.														
PMC131	<p>■ $\leq 0.5\% \text{ of } (\text{URL} - \text{LRL}) \times \text{TD}^1$</p> <p><i>Example: PMC131 version "A1R"</i></p> <ul style="list-style-type: none"> ■ Nominal value = 10 bar ■ Upper range value (URV) = 6 bar ■ Lower range value (LRV) = 0 bar <p><i>Turn down (is set at factory):</i></p> <ul style="list-style-type: none"> ■ Nominal value / $(\text{URV} - \text{LRV}) = 10 \text{ bar} / 6 \text{ bar} = 10:6$ 														
	 <p>P01-PMx13xxx-05-xx-xx-xx-001</p>														
PMP131 and PMP135	<p><i>Example: PMC131 version "A1R"</i> <i>set span: 0 to 6 bar; nominal value = 10 bar</i></p> <table style="margin-left: 20px;"> <tr> <td>1</td> <td>Span set and calibrated at the factory (measuring range)</td> </tr> <tr> <td>2</td> <td>Nominal value \cong Upper Range Limit (URL)</td> </tr> <tr> <td>3</td> <td>Sensor measuring range</td> </tr> <tr> <td>LRL</td> <td>Lower Range Limit</td> </tr> <tr> <td>URL</td> <td>Upper Range Limit</td> </tr> <tr> <td>LRV</td> <td>Lower Range Value</td> </tr> <tr> <td>URV</td> <td>Upper Range Value</td> </tr> </table>	1	Span set and calibrated at the factory (measuring range)	2	Nominal value \cong Upper Range Limit (URL)	3	Sensor measuring range	LRL	Lower Range Limit	URL	Upper Range Limit	LRV	Lower Range Value	URV	Upper Range Value
1	Span set and calibrated at the factory (measuring range)														
2	Nominal value \cong Upper Range Limit (URL)														
3	Sensor measuring range														
LRL	Lower Range Limit														
URL	Upper Range Limit														
LRV	Lower Range Value														
URV	Upper Range Value														
Rise time (T90)	PMC131 20 ms														
Settling time	PMP131 and PMP135 2 to 5 ms														

1) extended specifications apply to customer-specific measuring ranges

Thermal change of the lower range value and the span	PMC131²⁾
	Zero output, -20 to +85 °C: ■ typically 1.5 % of URL
	Output span, -20 to +85 °C: ■ Nominal value 0.4 to 40 bar: typically 0.8 % of URL ■ Nominal value 0.1bar: typically 1.0 % of URL

Temperature coefficient (T_K) for lower range value and span	PMP131 and PMP135 (analog output)
	Zero output: ■ typically: 0.2 % of URL/10 K ■ max.: 0.5 % of URL/10 K ■ Nominal value ≤ 6 bar: by 0.1 % of URL/10 K higher
	Output signal: ■ typically: 0.2 % of URL/10 K ■ max.: 0.5 % of URL/10 K
	PMP131 and PMP135 (switch output)
	Switch point: ■ typically: 0.2 % of URL/10 K ■ max.: 0.5 % of URL/10 K

Operating conditions (Installation instructions)

Orientation	anywhere
Installation instructions	PMP131 Process connection G 1/2 flush-mounted, max. torque 40 Nm
Location dependence	PMC131 without influence

PMP131 and PMP135
Position-dependent zero point shift can be corrected by potentiometer setting, see also Page 16.

2) for customer-specific measuring-ranges: values are doubled

Operating conditions (environment)

Ambient temperature range

PMC131
–20 to +85 °C

PMP131 and PMP135

- For non-hazardous areas: –25 to +70 °C
 - Ex i: –25 to +65 °C
-

Storage temperature range

PMC131
–50 to +100 °C

PMP131 and PMP135

–40 to +85 °C

Climate class

PMC131
4K4H as per DIN EN 60721-3

PMP131 and PMP135

4Z
with Z = 70 °C as per VDI/VDE 3540

Degree of protection

PMC131

- Plug M 16 x 1,5 (DIN 43650/A), ½ NPT: IP 65/NEMA 4X
- Plug M12x1: IP 65/ NEMA 4
- Cable: IP 68/NEMA 6P (1 mWS/24 h)

PMP131 and PMP135

- Plug M 16 x 1,5 (DIN 43650/A), ½ NPT: IP 65/NEMA 4X
 - Plug M 12x1 and gauge pressure sensors: IP 65/NEMA 4X
 - Plug M 12x1 and absolute pressure sensors: IP 68/NEMA 6P (1 mWS/24 h)
 - Cable: IP 68/NEMA 6P (1 mWS/24 h)
-

Vibration resistance

4M5 as per DIN EN 60721-3

Electromagnetic compatibility

PMC131

Interference emission as per EN 61326 electrical device class B,
Interference immunity as per EN 61326 appendix A (industrial use).

PMP131 and PMP135

Electromagnetic compatibility according to EN 61326;
For details refer to the declaration of conformity (see ATEX Safety Instructions XA142P)


Operating conditions (process)

Process temperature range	PMC131 <ul style="list-style-type: none"> ■ –20 to +100 °C ■ Devices for oxygen application: –10 to +60 °C (Version "S" for feature 30 "Sensor gasket") PMP131 –25 to +70 °C
PMP135	–25 to +100 °C (+135 °C for max. 1 hour) <p>Extreme jumps in temperature can result in temporary measuring errors. Temperature compensation takes effect after several minutes. Internal temperature compensation is faster the smaller the temperature jump and the longer the time interval.</p>
Overload resistance	→ See Page 18, "Ordering information" section.
Vacuum resistance	PMC131 <ul style="list-style-type: none"> ■ with URV > 200 mbar/> 80 inH₂O/> 1.5 psi: 0 mbar_{abs} ■ with URV = 200 mbar/= 50 inH₂O or 80 inH₂O: 500 mbar_{abs} (Versions "D12", "D38", "W6O", "S4N") ■ with URV = 20 mbar or 100 mbar/=1.5 psi/=15 inH₂O or 30 inH₂O: 700 mbar_{abs} (Versions "D10", "D3W", "D31", "Q4D", "V6F", "W6N", "W6R") PMP131 and PMP135 10 mbar _{abs}
Pressure specifications	<ul style="list-style-type: none"> ■ The MWP (maximum working pressure) of the device is specified on the nameplate. It depends on the weakest element, with regard to pressure, of the selected components. See the following sections: <ul style="list-style-type: none"> – → Page 18 ff, "Ordering information" section, feature 50 "Measuring range; MWP; Nominal value; OPL" or "Sensor range; MWP; OPL". – → Page 12 ff, "Mechanical construction" section. The MWP specification on the nameplate is based on a reference temperature of +20 °C and can be present over an unlimited period of time. ■ The test pressure corresponds to the overload limit of the measuring device (Over Pressure Limit OPL) and must only be present for a limited period of time.

Mechanical construction

PMC131

Housing




Housing PMC131; Material AISI 304 (1.4301)

- 1 Versions A1, A2, B1, C1, C2: Plug M 16 or $\frac{1}{2}$ NPT (ISO 4400), IP 65
- 2 Versions A5, B5, C5: Plug M 12, IP 65
- 3 Versions A3, A4, B3, C3: 5 m or 25 m cable, IP 68

→ See the following diagram for the height of process connection A

Process connections




Process connections PMC131; Material AISI 304 (1.4301)

- 1 Version 1: Thread ISO 228 G $\frac{1}{2}$
- 2 Version 2: Thread ANSI $\frac{1}{2}$ MNPT $\frac{1}{4}$ FNPT
- 3 Version 5: Thread ISO 228 G $\frac{1}{2}$, bore 11 mm

→ See respective housing for installation height H (previous figure)

PMP131 and PMP135

Housings



Housings PMP131 and PMP135; Material AISI 304 (1.4301)

1...3 PMP131 and PMP135 with sensor range up to 100 bar

4...6 PMP131 with sensor range up to 400 bar

1 + 4 Versions A1, A2: Plug M 16 (DIN 43650/A) or 1/2 NPT (ISO 4400), IP 65; dimension x = 52 mm
Version A5: Plug DIN 43650/C, IP 65; dimension x = 42 mm


2 + 5 Version A3: 5 m cable, IP 68

3 + 6 Version A4: Plug M 12, IP 65

→ See the following figure for the dimensions of process connection A

PMP131

Process connections



Process connections PMP131; Material AISI 304 (1.4301)

1 Version 1: Thread ISO 228 G 1/2

2 Version 2: Thread ANSI 1/2 MNPT 1/4 FNPT

3 Version 3: Thread ANSI 1/2 MNPT, bore 4 mm female


4 Version 4: Thread ISO 228 G 1/4

5 Version 5: Thread ANSI 1/4 MNPT, bore 3.5 mm female

6 Version 6: Thread M 20 x 1.5

→ See respective housing for installation height H (figure above)

→ Process connections with AF 27 mm




Process connection PMP131; Material AISI 304 (1.4301)

- 1 Version B: Thread ISO 228 G 1/2, Gasket DIN 3852-A flush-mounted
 2 Dimensions for tapped hole G 1/2 as per DIN 3852-11 form X

→ See respective housing for installation height H

PMP135

Process connections

Process connections PMP135; Material AISI 316L (1.4435); Surface roughness of the surfaces in contact with the medium $R_a \leq 0.8 \mu m$

M = Diaphragm diameter 17.2 mm

- 1 Version F: Clamp 3/4" (ISO 2852) or DN 22 (DIN 32676), 3A
 2 Version G: Tri-Clamp 1" to 1 1/2" (ISO 2852) or DN 25 to DN 40 (DIN 32676), 3A
 3 Version H: Tri-Clamp 2" (ISO 2852) or DN 50 (DIN 32676), 3A
 4 Version S: SMS 1 1/2" PN 25, 3A
 5 Version N: G1A (ISO 228), with sealing surface for flush-mounted installation
 6 Version M: G1A (ISO 228), with metallic sealing taper, flush-mounted


→ See respective housing for installation height H

Weights	<ul style="list-style-type: none"> ■ PMC131: approx. 0.32 kg ■ PMP131: approx. 0.24 kg ■ PMP135: approx. 0.34 kg
Material	<ul style="list-style-type: none"> ■ Process connection: <ul style="list-style-type: none"> – PMC131: AISI 304 (1.4301) – PMP131: AISI 304 (1.4301) – PMP135: AISI 316L (1.4435) ■ Sensor diaphragm: <ul style="list-style-type: none"> – PMC131: Ceraphire® (99.9 % Al₂O₃), FDA number 21-CFR 186.1256 – PMP131, PMP135: AISI 316L (1.4435) ■ Fill oil: <ul style="list-style-type: none"> – PMP131: Tegiloxan 3 – PMP135: Mineral oil, FDA number 21-CFR 172.882 ■ Housing AISI 304 (1.4301) ■ Electrical connection Plug M12: Polyamide (PA) Valve connector: Sheathing made of polyamide (PA) Cable: Sheathing made of polyurethane (PUR/UL94, V0, UV-resistant)

Operating elements


Operating elements

Position of operating elements



The potentiometer for operating the Cerabar T PMP131 and PMP135 with analog or switch output is located below the base of the plug.


Analog output: Zero point adjustment



The zero point can be corrected for the Cerabar T PMP131 and PMP135 with analog output and plug version.

1 Potentiometer for zero point correction by $\pm 5\%$ of URL


Switch output: Switch point and hysteresis adjustment



For the Cerabar T PMP131 and PMP135 with switch output, both the switch point and hysteresis can be adjusted.

This can also be carried out at atmospheric pressure using the enclosed test cable and a voltmeter.

- 1 Hysteresis adjustment 1.5 to 20 % of URL;
Factory setting 10 % of URL
- 2 Switch point adjustment 0 to 100 % of URL;
Factory setting 50 % of URL
- 3 LED color code for checking the switch status:
green = off; red = on
- 4 Connect voltmeter to test pins:
0 to 1 V corresponds to 0 to 100 % of URL



Instructions for switch point and hysteresis (the percentage values refer to the URL)

U_a Output voltage
 p Acting pressure

Certificates and approvals

CE mark	The device meets the legal requirements of the EC directives. Endress+Hauser confirms that the device has been successfully tested by applying the CE mark.
Ex approvals	All explosion protection data are given in separate documentation which is available upon request. The Ex documentation is supplied as standard with all devices approved for use in explosion hazardous areas. → See also Page 22, "Safety Instructions" section.
Pressure Equipment Directive (PED)	This measuring device corresponds to Article 3 (3) of the EC directive 97/23/EC (Pressure Equipment Directive) and has been designed and manufactured according to good engineering practice.
Functional safety SIL 2	The Cerabar T PMP131 and PMP135 pressure transducers with 4 to 20 mA electronics have been assessed by an independent body according to the standards IEC 61508/IEC 61511-1. These devices can be used for monitoring process pressure up to SIL 2. → For a detailed description of safety functions with Cerabar T, settings and characteristic quantities for functional safety, see the "Functional Safety Manual – Cerabar T SD160P".
Suitability for hygienic processes	<p>The Cerabar T PMP135 is suitable for the employment in hygienic processes.</p> <p>An overview of permitted process connections on page 14.</p> <p>Many versions meet the requirements of 3A-Sanitary Standard No. 74 and are certified by the EHEDG.</p> <p> Note! The gap-free connections can be cleaned without residue using the usual cleaning methods.</p>  
TSE Certificate of Suitability	<p>Cerabar T PMP135</p> <p>The following applies to wetted device components: They do not contain any materials derived from animals. No auxiliaries or operating materials derived from animals are used in production or processing. Process wetted device components are listed in the "Mechanical construction" and "Ordering information" sections.</p>
Standards and guidelines	<p>DIN EN 60770 (IEC 60770): Transmitters for controlling in systems used in industrial process technology Part 1: Methods for evaluating the operating behavior.</p> <p>DIN EN 61003-1, Edition:1993-12 Systems used in industrial process technology; Devices with analog inputs and two-point or multi-point behavior; Part 1: Methods for evaluating the operating behavior.</p> <p>DIN 16086: Electrical pressure measuring devices, pressure sensors, transmitters, pressure measuring devices Terms, specifications in data sheets.</p> <p>IEC 60592 Degrees of protection provided by enclosures (IP-Code).</p> <p>EN 61326: Electrical equipment for control technology and laboratory application – EMC requirements.</p> <p>IEC 61010 Safety requirements for electrical equipment for measurement, control and laboratory use.</p> <p>NAMUR Association for Standards for Control and Regulation in the Chemical Industry.</p>
Registered trademarks	<p>Ceraphire® Registered trademark of Endress+Hauser GmbH+Co. KG, Maulburg, Germany (→ see also www.endress.com/ceraphire)</p>

Ordering information

PMC131

	10	Electrical connection:				
	A1	Plug ISO 4400, M 16, IP 65/NEMA 4X				
	A2	Plug ISO 4400, $\frac{1}{2}$ NPT, IP 65/NEMA 4X				
	A3	5 m cable, IP 68/NEMA 6P				
	A4	25 m cable, IP 68/NEMA 6P				
	A5	Plug M 12, IP 65/NEMA 4				
	B1	Plug ISO 4400, M 16, IP 65, ATEX II 3 G EEx nA II T4				
	B3	5 m cable, IP 68, ATEX II 3 G EEx nA II T4				
	B5	Plug M 12, IP 65, ATEX II 3 G EEx nA II T4				
	C1	Plug ISO 4400, M 16, NEMA 4X, CSA GP				
	C2	Plug ISO 4400, $\frac{1}{2}$ NPT, NEMA 4X, CSA GP				
	C3	5m cable, IP 68/NEMA 6P, CSA GP				
	C5	Plug M12, IP 65/NEMA 4, CSA GP				
	20	Process connection:				
	1	Thread ISO 228 G $\frac{1}{2}$, AISI 304				
	2	Thread ANSI $\frac{1}{2}$ MNPT $\frac{1}{4}$ FNPT, AISI 304				
	5	Thread ISO 228 G $\frac{1}{2}$ bore 11 mm, AISI 304				
	30	Sensor seal:				
	F	FKM Viton				
	S	FKM Viton, oxygen application				
	40	Additional options:				
	1	Without additional equipment				
	S	GL (German Lloyd) marine certificate				
	2	Final inspection report				
	50	Measuring range; MWP; Nominal value; OPL:				
			Measuring range	MWP (Maximum Working Pressure)	Nominal value	OPL (Over Pressure Limit)
			Sensors for gauge pressure			
		A1G	0 to 1 bar / 0 to 100 kPa	6.7 bar	1 bar	10 bar / 1 MPa
		A1H ¹⁾	0 to 1.6 bar / 0 to 160 kPa	12 bar	2 bar	18 bar / 1.8 MPa
		A1K	0 to 2 bar / 0 to 200 kPa	12 bar	2 bar	18 bar / 1.8 MPa
		A1Q	0 to 4 bar / 0 to 400 kPa	16.7 bar	4 bar	25 bar / 2.5 MPa
		A1R ¹⁾	0 to 6 bar / 0 to 600 kPa	26.7 bar	10 bar	40 bar / 4 MPa
		A1S	0 to 10 bar / 0 to 1 MPa	26.7 bar	10 bar	40 bar / 4 MPa
		A1T ¹⁾	0 to 16 bar / 0 to 1.6 MPa	26.7 bar	20 bar	40 bar / 4 MPa
		A1V	0 to 20 bar / 0 to 2 MPa	26.7 bar	20 bar	40 bar / 4 MPa
		A1W ¹⁾	0 to 25 bar / 0 to 2.5 MPa	40 bar	40 bar	60 bar / 6 MPa
		A1X	0 to 40 bar / 0 to 4 MPa	40 bar	40 bar	60 bar / 6 MPa
		A3C ¹⁾	-1 to 0 bar / -100 to 0 kPa	6.7 bar	2 bar	10 bar / 1 MPa
		A3E ¹⁾	-1 to 1 bar / -100 to 100 kPa	6.7 bar	2 bar	10 bar / 1 MPa
		A3G ¹⁾	-1 to 3 bar / -100 to 300 kPa	16.7 bar	4 bar	25 bar / 2.5 MPa
		A3K ¹⁾	-1 to 9 bar / -100 to 900 kPa	26.7 bar	10 bar	40 bar / 4 MPa
		A3N ¹⁾	-1 to 15 bar / -0.1 to 1.5 MPa	26.7 bar	20 bar	40 bar / 4 MPa
		D10	0 to 100 mbar / 0 to 10 kPa	2.7 bar	0.1 bar	4 bar / 400 kPa
		D12 ¹⁾	0 to 200 mbar / 0 to 20 kPa	3.3 bar	0.2 bar	5 bar / 500 kPa
		D14	0 to 400 mbar / 0 to 40 kPa	5.3 bar	0.4 bar	8 bar / 800 kPa
		D3W	-20 to 20 mbar / -2 to 2 kPa	2.7 bar	0.2 bar	4 bar / 400 kPa
		D31 ¹⁾	-100 to 100 mbar / -10 to 10 kPa	3.3 bar	0.2 bar	5 bar / 500 kPa
		D38 ¹⁾	-200 to 200 mbar / -20 to 20 kPa	3.3 bar	0.4 bar	5 bar / 500 kPa
		D39 ¹⁾	-300 to 300 mbar / -30 to 30 kPa	5.3 bar	1 bar	8 bar / 800 kPa
		PMC131				Order code

→ For continuation of ordering information of PMC131, see the following page.

1) Span set and calibrated at the factory

PMC131 (continued)

50		Measuring range; MWP; Nominal value; OPL:					
				Measuring range	MWP (Maximum Working Pressure)	Nominal value	OPL (Over Pressure Limit)
Sensors for gauge pressure							
Q4D	0 to 1.5 psi	40 psi	1.5 psi	60 psi			
Q4F ¹⁾	0 to 5 psi	80 psi	6 psi	120 psi			
Q4H	0 to 15 psi	100 psi	15 psi	150 psi			
Q4K	0 to 30 psi	180 psi	30 psi	270 psi			
Q4N ¹⁾	0 to 50 psi	250 psi	60 psi	375 psi			
Q4R	0 to 150 psi	400 psi	150 psi	600 psi			
Q4S	0 to 300 psi	400 psi	300 psi	600 psi			
Q4T ¹⁾	0 to 500 psi	600 psi	600 psi	900 psi			
V6F ¹⁾	-1.5 to 1.5 psi	50 psi	3 psi	75 psi			
V6N ¹⁾	-15 to 15 psi	100 psi	30 psi	150 psi			
V6R ¹⁾	-15 to 30 psi	250 psi	60 psi	375 psi			
V6S	-15 to 60 psi	250 psi	60 psi	375 psi			
V6V	-15 to 150 psi	400 psi	150 psi	600 psi			
S4N ¹⁾	0 to 50 inH ₂ O	50 psi	3 psi	75 psi			
S4Q ¹⁾	0 to 100 inH ₂ O	80 psi	6 psi	120 psi			
W6N ¹⁾	-15 to 15 inH ₂ O	40 psi	3 psi	60 psi			
W6O ¹⁾	-80 to 80 inH ₂ O	50 psi	6 psi	75 psi			
W6R ¹⁾	-15 to 30 inH ₂ O	50 psi	3 psi	75 psi			
Sensors for absolute pressure							
A2G	0 to 1 bar / 0 to 100 kPa	6.7 bar	1 bar	10 bar / 1 MPa			
A2H ¹⁾	0 to 1.6 bar / 0 to 160 kPa	12 bar	2 bar	18 bar / 1.8 MPa			
A2K	0 to 2 bar / 0 to 200 kPa	12 bar	2 bar	18 bar / 1.8 MPa			
A2Q	0 to 4 bar / 0 to 400 kPa	16.7 bar	4 bar	25 bar / 2.5 MPa			
A2R ¹⁾	0 to 6 bar / 0 to 600 kPa	26.7 bar	10 bar	40 bar / 4 MPa			
A2S	0 to 10 bar / 0 to 1 MPa	26.7 bar	10 bar	40 bar / 4 MPa			
A2T ¹⁾	0 to 16 bar / 0 to 1.6 MPa	26.7 bar	20 bar	40 bar / 4 MPa			
A2V	0 to 20 bar / 0 to 2 MPa	26.7 bar	20 bar	40 bar / 4 MPa			
A2W ¹⁾	0 to 25 bar / 0 to 2.5 MPa	40 bar	40 bar	60 bar / 6 MPa			
A2X	0 to 40 bar / 0 to 4 MPa	40 bar	40 bar	60 bar / 6 MPa			
D20 ¹⁾	0 to 100 mbar / 0 to 10 kPa	3.3 bar	0.2 bar	5 bar / 500 kPa			
D22	0 to 200 mbar / 0 to 20 kPa	3.3 bar	0.2 bar	5 bar / 500 kPa			
D24	0 to 400 mbar / 0 to 40 kPa	5.3 bar	0.4 bar	8 bar / 800 kPa			
R4D ¹⁾	0 to 1.5 psi	50 psi	3 psi	75 psi			
R4F ¹⁾	0 to 5 psi	80 psi	6 psi	120 psi			
R4H	0 to 15 psi	100 psi	15 psi	150 psi			
R4K	0 to 30 psi	180 psi	30 psi	270 psi			
R4N ¹⁾	0 to 50 psi	250 psi	60 psi	375 psi			
R4R	0 to 150 psi	400 psi	150 psi	600 psi			
R4S	0 to 300 psi	400 psi	300 psi	600 psi			
R4T ¹⁾	0 to 500 psi	600 psi	600 psi	900 psi			

PMC131 Complete order code

1) Span set and calibrated at the factory

PMP131

10	Electrical connection:		
A1	Plug ISO 4400, M 16, IP 65/NEMA 4X (DIN 43650/A)		
A2	Plug ISO 4400, ½ NPT, IP 65/NEMA 4X		
A3	5 m cable, IP 68/NEMA 6P		
A4	Plug M 12, IP 65/NEMA 4X		
A5	Plug DIN 43650/C, IP65, NEMA 4X		
20	Process connection:		
B	Thread ISO 228 G ½, Seal DIN 3852, AISI 304, flush-mounted		
1	Thread ISO 228 G ½, AISI 304		
2	Thread ANSI ½ MNPT ¼ FNPT, AISI 304		
3	Thread ANSI ½ MNPT bore 4 mm, AISI 304		
4	Thread ISO 228 G ¼, AISI 304		
5	Thread ANSI ¼ MNPT bore 3.5 mm, AISI 304		
6	Thread M 20 x 1.5		
30	Output:		
0	Analog current output 4 to 20 mA, SIL		
D	Analog current output 4 to 20 mA, SIL, ATEX II 1/2 G EEx ib IIC T6		
1	Analog current output 4 to 20 mA, SIL, ATEX II 2 G EEx ib IIC T6		
5	Analog current output 4 to 20 mA, SIL, ATEX II 3 G EEx nA II T6		
2	Switch output PNP, 3-wire		
3	Switch output PNP, 3-wire, ATEX II 3 G EEx nA II T6		
6	Analog voltage output 0...10 V		
40	Additional options:		
1	Without additional equipment		
S	GL/RINA marine approval		
2	Final inspection report		
50	Sensor range; MWP; OPL:		
		Sensor range	MWP (maximum working pressure)
		Sensors for gauge pressure	OPL (over pressure limit)
		A1G 0 to 1 bar / 0 to 100 kPa	2.7 bar 4 bar / 400 kPa
		A1H 0 to 1.6 bar / 0 to 160 kPa	4 bar 6.4 bar / 640 kPa
		A1N 0 to 2.5 bar / 0 to 250 kPa	6.7 bar 10 bar / 1 MPa
		A1Q 0 to 4 bar / 0 to 400 kPa	10.7 bar 16 bar / 1.6 MPa
		A1R 0 to 6 bar / 0 to 600 kPa	16 bar 24 bar / 2.4 MPa
		A1S 0 to 10 bar / 0 to 1 MPa	25 bar 40 bar / 4 MPa
		A1T 0 to 16 bar / 0 to 1.6 MPa	25 bar 64 bar / 6.4 MPa
		A1W 0 to 25 bar / 0 to 2.5 MPa	25 bar 100 bar / 10 MPa
		A1X 0 to 40 bar / 0 to 4 MPa	60 bar 160 bar / 16 MPa
		A1Z 0 to 60 bar / 0 to 6 MPa	60 bar 240 bar / 24 MPa
		A70 0 to 100 bar / 0 to 10 MPa	100 bar 400 bar / 40 MPa
		A71 0 to 160 bar / 0 to 16 MPa	160 bar 600 bar / 60 MPa
		A73 0 to 250 bar / 0 to 25 MPa	250 bar 600 bar / 60 MPa
		A74 0 to 400 bar / 0 to 40 MPa	400 bar 600 bar / 60 MPa
		Q4H 0 to 15 psi	40 psi 60 psi
		Q4K 0 to 30 psi	100 psi 150 psi
		Q4N 0 to 50 psi	160 psi 240 psi
		Q4R 0 to 150 psi	400 psi 600 psi
		Q4S 0 to 300 psi	400 psi 1500 psi
		Q4T 0 to 500 psi	1000 psi 2400 psi
		Q4V 0 to 1000 psi	1000 psi 3600 psi
		Q70 0 to 1500 psi	1500 psi 6000 psi
		Q73 0 to 3000 psi	3000 psi 9000 psi
		Q74 0 to 6000 psi	6000 psi 9000 psi
PMP131 Order code			

→ For continuation of ordering information of PMP131, see the following page.

PMP131 (continued)

50				Sensor range; MWP; OPL:		
				Sensor range	MWP (maximum working pressure)	OPL (over pressure limit)
				Sensors for absolute pressure		
				A2G 0 to 1 bar / 0 to 100 kPa	2.7 bar	4 bar / 400 kPa
				A2H 0 to 1.6 bar / 0 to 160 kPa	4 bar	6.4 bar / 640 kPa
				A2N 0 to 2.5 bar / 0 to 250 kPa	6.7 bar	10 bar / 1 MPa
				A2Q 0 to 4 bar / 0 to 400 kPa	10.7 bar	16 bar / 1.6 MPa
				A2R 0 to 6 bar / 0 to 600 kPa	16 bar	24 bar / 2.4 MPa
				A2S 0 to 10 bar / 0 to 1 MPa	25 bar	40 bar / 4 MPa
				A2T 0 to 16 bar / 0 to 1.6 MPa	25 bar	64 bar / 6.4 MPa
				A2W 0 to 25 bar / 0 to 2.5 MPa	25 bar	100 bar / 10 MPa
				A2X 0 to 40 bar / 0 to 4 MPa	60 bar	160 bar / 16 MPa
				A2Z 0 to 60 bar / 0 to 6 MPa	60 bar	240 bar / 24 MPa
				B70 0 to 100 bar / 0 to 10 MPa	100 bar	400 bar / 40 MPa
				B71 0 to 160 bar / 0 to 16 MPa	160 bar	600 bar / 60 MPa
				B73 0 to 250 bar / 0 to 25 MPa	250 bar	600 bar / 60 MPa
				B74 0 to 400 bar / 0 to 40 MPa	400 bar	600 bar / 60 MPa
				R4H 0 to 15 psi	40 psi	60 psi
				R4K 0 to 30 psi	100 psi	150 psi
				R4N 0 to 50 psi	160 psi	240 psi
				R4R 0 to 150 psi	400 psi	600 psi
				R4S 0 to 300 psi	400 psi	1500 psi
				R4T 0 to 500 psi	1000 psi	2400 psi
				R4V 0 to 1000 psi	1000 psi	3600 psi
				R70 0 to 1500 psi	1500 psi	6000 psi
				R73 0 to 3000 psi	3000 psi	9000 psi
				R74 0 to 6000 psi	6000 psi	9000 psi
PMP131					Complete order code	


PMP135

10	Electrical connection:		
	A1 Plug ISO 4400, M 16, IP 65/NEMA 4X		
	A2 Plug ISO 4400, ½ NPT, IP 65/NEMA 4X		
	A3 5 m cable, IP 68/NEMA 6P		
	A4 Plug M 12, IP 65/NEMA 4X		
20	Process connection:		
	F Clamp ISO 2852, DN 22 (¾"), AISI 316L, 3A, DIN 32676 DN 20, EHEDG		
	G Tri-Clamp ISO 2852, DN 25 to 38 (1" to 1½"), AISI 316L, 3A, DIN 32676 DN 25 to 40, EHEDG		
	H Tri-Clamp ISO 2852, DN 40 to 51 (2"), AISI 316L, 3A, DIN 32676 DN 50, EHEDG		
	M Thread ISO 228, G 1, with metallic sealing taper, AISI 316L, flush-mounted, adapter 52005087		
	N Thread ISO 228, G 1, with sealing surface for flush-mounted installation, AISI 316L, adapter 52001051		
	S SMS 1½", PN 25, AISI 316L, 3A, EHEDG		
30	Output:		
	0 Analog 4 to 20 mA, SIL		
	D Analog 4 to 20 mA, SIL, ATEX II 1/2 G EEx ib IIC T6		
	1 Analog 4 to 20 mA, SIL, ATEX II 2 G EEx ib IIC T6		
	5 Analog 4 to 20 mA, SIL, ATEX II 3 G EEx nA II T6		
	2 Switch output PNP, 3-wire		
	3 Switch output PNP, ATEX II 3 G EEx nA II T6		
40	Additional options:		
	1 Without additional equipment		
	C EN10204-3.1 material (wetted) inspection certificate		
	2 Final inspection report		
50	Sensor range; MWP; OPL:		
		Sensor range	MWP (maximum working pressure)
		Sensors for gauge pressure	OPL (over pressure limit)
	A1G	0 to 1 bar / 0 to 100 kPa	2.7 bar
	A1H	0 to 1.6 bar / 0 to 160 kPa	4 bar
	A1N	0 to 2.5 bar / 0 to 250 kPa	6.7 bar
	A1Q	0 to 4 bar / 0 to 400 kPa	10.7 bar
	A1R	0 to 6 bar / 0 to 600 kPa	16 bar
	A1S	0 to 10 bar / 0 to 1 MPa	25 bar
	A1T	0 to 16 bar / 0 to 1.6 MPa	25 bar
	A1W	0 to 25 bar / 0 to 2.5 MPa	25 bar
	A1X	0 to 40 bar / 0 to 4 MPa	60 bar
	Q4H	0 to 15 psi	40 psi
	Q4K	0 to 30 psi	100 psi
	Q4N	0 to 50 psi	160 psi
	Q4R	0 to 150 psi	400 psi
	Q4S	0 to 300 psi	400 psi
	Q4T	0 to 500 psi	1000 psi
	Sensors for absolute pressure		
	A2G	0 to 1 bar / 0 to 100 kPa	2.7 bar
	A2H	0 to 1.6 bar / 0 to 160 kPa	4 bar
	A2N	0 to 2.5 bar / 0 to 250 kPa	6.7 bar
	A2Q	0 to 4 bar / 0 to 400 kPa	10.7 bar
	A2R	0 to 6 bar / 0 to 600 kPa	16 bar
	A2S	0 to 10 bar / 0 to 1 MPa	25 bar
	A2T	0 to 16 bar / 0 to 1.6 MPa	25 bar
	A2W	0 to 25 bar / 0 to 2.5 MPa	25 bar
	A2X	0 to 40 bar / 0 to 4 MPa	60 bar
	R4H	0 to 15 psi	40 psi
	R4K	0 to 30 psi	100 psi
	R4N	0 to 50 psi	160 psi
	R4R	0 to 150 psi	400 psi
	R4S	0 to 300 psi	400 psi
	R4T	0 to 500 psi	1000 psi
PMP135		Complete order code	

Accessories

Welding neck with sealing taper

- Welding neck for flush-mounted installation of the process connection G1 A with metallic sealing taper (PMP135, version M)
Material: AISI 316L (1.4435)
Order number: 52005087
- with inspection certificate 3.1
Order number: 52010171




P01-PMP135xx-00-xx-00-xx-002

- Pressure sensor dummy for welding the welding neck without any problems with order number 52005087 or 52010171
Material: CuZn
Order number: 52005272

Welding neck with sealing surface


- Welding neck for flush-mounted installation of the process connection G1 A with sealing surface (PMP135, version N)
Material: AISI 316L (1.4435)
Gasket (enclosed): silicone O-ring
Order number: 52001051
- Optional with inspection certificate 3.1
Order number: 52011896



P01-PMP13xxx-00-xx-00-xx-005

Plug-in jack


- Plug-in jack M 12x1, straight
Self-made connection to M 12x1 housing plug
Material: Handle body PA; Coupling nut CuZn, nickel-plated, degree of protection (inserted): IP 67
Order number: 52006263



P01-PMP13xxx-00-xx-00-xx-003

Plug-on display PHX20/PHX21

- 4-digit red LED display for looping into 4 to 20 mA circuit via elbow plug
DIN 43650, rotatable in 90° steps, programmable via 2 keys
Display range: -1999 to +9999
Degree of protection: IP 65
Material: Housing Pa6 GF30, front screen PMMA
Voltage drop: ≤5 V (corresponds to max. 250 Ω load)
Approval for PHX21: ATEX II 2G
Order number PHX20: 52022914
Order number PHX21: 52022915



P01-PHX2xxxx-00-xx-xx-xx-002

Documentation

Field of Activities	■ Pressure measurement, powerful measuring devices for process pressure, differential pressure, level and flow: FA004P/00/en
Technical Information	■ EMC test procedures: TI241F/00/en
Operating Instructions	■ Cerabar T PMC131: KA085P/00/a3 ■ Cerabar T PMP131: KA103P/00/a3 ■ Cerabar T PMP135: KA198P/00/a3
Functional Safety Manual (SIL)	■ Cerabar T PMP131, PMP135: SD160P/00/en
Safety Instructions	Cerabar T PMC131 ■ ATEX II 3 G EEx nA II T4: XA191P/00/a3 Cerabar T PMP131 ■ ATEX II 1/2 G or 2 G EEx ib IIC T6: XA142P/00/a3 ■ ATEX II 3 G EEx nA II T6: XA191P/00/a3 Cerabar T PMP135 ■ ATEX II 1/2 G or 2 G EEx ib IIC T6: XA142P/00/a3 ■ ATEX II 3 G EEx nA II T6: XA191P/00/a3

Instruments International

Endress+Hauser
Instruments International AG
Kaegenstrasse 2
4153 Reinach
Switzerland

Tel. +41 61 715 81 00
Fax +41 61 715 25 00
www.endress.com
info@ii.endress.com

Endress+Hauser 
People for Process Automation